VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-2959	DATE	November 26 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The engine control unit (DME) takes a longer time for the catalyzer heating period when the valvetronic has a defect. During this period, exhaust gas values may exceed the emission thresholds because the catalyzer could not fully purify the combustion gases until the catalyzer heating ends.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-8E20	BMW 330e	2015 - 2018	1,502
ABA-JR20	BMW 530i	2018	7
CLA-JA20P	BMW 530e iPerformance	2017 - 2018	997
ABA-JT20	BMW 530 Touring	2018	5
ABA-JX20S	BMW 630i Gran tourismo	2018	10
DLA-7D20	BMW 740e iPerfomance	2016 -2 018	1,219
		TOTAL	3,740