

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2960	DATE	November 26 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A replacement part (steering wheel with Takata airbag, or the airbag inflator itself) relevant to former recalls may possibly have been installed, since they are compatible with the originally installed parts. It cannot be ruled out that, in case the airbag is activated during a crash, the inflator ruptures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-AT18	BMW 316ti	2001 - 2002	462
GH-AU20	BMW 318ti	2001 - 2002	446
GH-AV30	BMW 330Ci Cabriolet	2000	9
		TOTAL	917