

VEHICLE SAFETY/~~POLLUTION~~ RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3761	DATE	1/31/2024
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Volvo Cars investigations have identified that concerned vehicles may have a fault code set incorrectly, causing a temporary loss of the rear left hand turn signal		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC40]	2024	2,836
		TOTAL	2,836