

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3753	Date	Jan. 23, 2024
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The vehicles with the Belt Integrated Starter Generator (BISG) goes into fail safe mode on first startup, resulting in no charging of the 48V and 12V battery. Update the Starter Generator Control Module (SGCM).		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-DC2NC	F-PACE	2023-2024	29
3CA-DF2NB	E-PACE	2024	7
3CA-JB2ND	XF		4
3CA-JBS2ND	XF		1
3AA-L123UA	Range Rover Sport		2023
3AA-LR3UB	Discovery	6	
3CA-L123WA	Range Rover Sport	2023-2024	769
3CA-LC2ND	Discovery Sport	2023	27
3CA-LE62WAB	DEFENDER 90	2024	14
3CA-LE62WCB			1
3CA-LE72WAB	DEFENDER 110 DEFENDER 130	2023-2024	2,279
3CA-LE72WCB	DEFENDER 110		322
3CA-LK93WA	Range Rover	2023	404
3CA-LR3WB	Discovery	2023-2024	75
3CA-LY2NAC	Range Rover Velar		116
3CA-LY2NCC			28
3CA-LZ2NB	Range Rover Evoque	2023	25
		2023-2024	4,278

(JIS A4 size)