

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3741	DATE	16.02.2024
MANUFACTURE	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	With regards to the oil delivery pipe to the turbocharger, Due to improper manufacturing control during the pipe molding, the pipes might not meet the specified values. As a result, the pipe may crack at the part does not meet the specified values and leak the oil. In the worst case, there is a risk of the fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-173H	SF90Stradale	MY2023	23 cars
	SF90Spider	MY2023	82 cars
		TOTAL	105 cars