

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3757	DATE	2024/2/8
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain A-Class (177 platform), B-Class (247 platform), CLA (118 platform), C-Class (205 platform), CLS (257 platform), E-Class Saloon (213 platform), E-Class Coupe (238 platform), GLC (253 platform), GLE (167 platform), S-Class (222 platform, 223 platform) and G-Class (463 platform) vehicles with 4- or 6-cylinder diesel engine, the software of the engine control unit might not meet specifications.</p> <p>In case of a malfunction of the mass air flow sensor or the low-pressure exhaust gas recirculation valve, the malfunction indicator lamp (MIL) could incorrectly not illuminate or illuminate delayed. In this case, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-177012	A200d	2019	2,061
		2020	3,325
		2021	131
3DA-177012M	A200d	2019	1
-177084-			2
3DA-177112	A200d Sedan	2020	776
3DA-177112M		2021	20
3DA-247012		2020	1
3DA-247012M	B200d		3,014
3DA-118312M		2021	284
3DA-118612M	CLA200d Shooting Brake	2020	1
			3,331
		2021	690
3DA-118312M	CLA200d Shooting Brake	2020	1,691
3DA-118612M		2021	383

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-247713M	GLA200d 4MATIC	2020	1,074
		2021	1,711
3DA-247612M	GLB200d	2020	2,163
		2021	1,957
3DA-247613M	GLB200d 4MATIC		8
3DA-213004C	E220d		1
3MA-213016	E350de		24
3MA-213016C			4
LDA-222035	S400d 4MATIC	2019	2
LDA-222135			4
		TOTAL	22,659