

VEHICLE SAFETY/~~POLLUTION~~ RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3760	DATE	8/2/2024
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Volvo Cars quality investigations have identified that the screw joints for the second seat row belt buckles and lower belt anchorages may not have been torqued to the correct specification.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC90]	2020	4
VOLVO	[XC90]	2019~2020	2
VOLVO	[XC90]	2020~2023	21
VOLVO	[XC90]	2024	1
VOLVO	[XC90]	2021~2023	13
VOLVO	[XC90]	2023	6
VOLVO	[XC90]	2021	1
VOLVO	[XC90]	2016~2020	20
VOLVO	[XC90]	2017	1
		TOTAL	69