

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2 5 2 2	DATE	April 15, 2010
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	NUT IS POSSIBLE TO LOOSE BECAUSE DIFFERENT PARTS WERE INSTALLED ON FIXED NUT OF CLUTCH AXLE OF POWER TRANSMISSION FOR AGRICULTURAL TRACTOR. THEREFORE, THERE IS DIFFERENT POWER OF TRANSMISSION BETWEEN RIGHT AND LEFT SIDE, THIS SITUATION POSSIBLE TO CAUSE STEERING INSTABILITY OF TRACTOR.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
T130F	TPC153	2009-2010	10
T147F	TPC183	2009	3
T155F	TPC213	2009-2010	2
TOTAL			15