

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2 5 3 1	DATE	May 13, 2010
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Noise prevention equipment of Agricultural tractor have problem that strength of exhaust pipe is not enough, exhaust pipe interfere tractor hood, tightening strength of clamp for exhaust pipe is not enough. Because of these situation, if operator continue to use tractor, exhaust pipe will have crack, in worst case pipe could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
T131F	TJ75	2001-2003	387
T137F	TJ75	2003	263
SB-T137F	TJ75 TJ65 TJ55	2003-2005	788
SB-T150F	TJ55AT	2005-2009	433
SB-T150F	CT55H	2007-2009	22
TOTAL			1893