

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI 1692	DATE	Jul. 23. 2010
MANUFACTURER	Toyo trailer. co., ltd		
DESCRIPTION OF DEFECT	The material of the Stabilizer is trouble, so strength is insufficient. In the worst case, it becomes impossible for the car to run because of the arms damage. We exchange concerned arms to regular goods.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
THT	Semitrailer	2004 ~ 2006	LT1FB13374C007923 LT1FB13394C007924 LT1FB12314C011404 LT1FB123X4C011403 LT1FB12364C011401 LT1FB12384C011402 LT1FB12394C011439 LT1FB13384C011222 LT1FB12384C011223 LT1FB123X4C011224 LT1FB13315C005229 LT1FB13385C005227 LT1FB133X5C005228 LT1FB12344C011400 LT1FB12374C011407 LT1FB12334C011405 LT1FB13365C010040 LT1FB13315C009670 LT1FB123X4C011398 LT1FB12365C011688 LT1FB12314C011399 LT1FB12354C011406 LT1FB12354C011440
FAW	Semitrailer	2005 ~ 2007	LFTVM000X5AC03008 LFTVM00085AC03007 LFTVM00065AC03006 LFTVM00076AE03099 LFTVM00025AC03004 LFTVM00045AC03005
			TOTAL 29