

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1790	DATE	Oct. 25, 2011
MANUFACTURER	S&T Motors Co., Ltd. (Japanese Importer: Japan Auto Press Co., Ltd.)		
DESCRIPTION OF DEFECT	Some brake pads have defect that contact of lining and back-plate is unsuitable by reason of pad material. When the pad has been used for long, the lining is separated from the back-plate and the braking force is deteriorated. In worst case, the lining fall off and the brakes don' t work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GT250R	GT250R	2007 - 2010	1402
GT250	GT250	2007 - 2010	528
GT125R	GT125R	2008	1
GT125	GT125	2008	18
GV250	GV250	2009 - 2010	740
GV125C	GV125C	2008 - 2010	409
RT125D	RT125D	2007 - 2010	349
RX125SM	RX125SM	2007 - 2008	475
RX125D	RX125D	2007	188
		TOTAL	4110