

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 8 6 0	DATE	NOV. 28 2011
MANUFACTURER	NIPPON SHARYO.LTD.		
DESCRIPTION OF DEFECT	Due to incorrect procedure of bending the bracket for mounting fire-extinguisher box on LPG vehicles, the impact force during running causes high stress, so the crack occurs to this bracket. If it is continued to run, fire-extinguisher box may miss, and it may interfere with other traffic safety.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
BDG-FC6JEW A	R A N G E R	FC6JEW-10419 May. 7 2008	1
		FC6JEW-10428 May. 16 2008	1
		FC6JEW-10462~FC6JEW-10471 Apr. 22 2008~Jun. 26 2008	10
		FC6JEW-10478 Jun. 21 2008	1
		FC6JEW-10495~FC6JEW-10504 Jun. 26 2008~Aug. 26 2008	10
		FC6JEW-10508~FC6JEW-10509 Sep. 11 2008~Oct. 14 2008	2
		FC6JEW-10520~FC6JEW-10522 Sep. 15 2008~Sep. 22 2008	3
		FC6JEW-10524~FC6JEW-10529 Sep. 19 2008~Sep. 30 2008	6
		FC6JEW-10531 Nov. 27 2008	1
		FC6JEW-10534~FC6JEW-10536 Nov. 19 2008~Dec. 12 2008	3
		FC6JEW-10540~FC6JEW-10546 Dec. 19 2008~Mar. 16 2009	7
		FC6JEW-10548~FC6JEW-10549 Feb. 18 2009~Mar. 20 2009	2
		FC6JEW-10551~FC6JEW-10558 Feb. 21 2009~Sep. 25 2009	8
		FC6JEW-10591~FC6JEW-10600 May. 30 2009~Dec. 15 2009	10
		FC6JEW-12002~FC6JEW-12011 Sep. 1 2009~Dec. 23 2009	10
FC6JEW-12026~FC6JEW-12035 Dec. 17 2009~Aug. 5 2010	10		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
BDG-FC6JEWA	R A N G E R	FC6JEW-12041 Jun. 18 2010	1
		FC6JEW-12043~FC6JEW-12044 Jul. 15 2010~Sep. 10 2010	2
		FC6JEW-12046~FC6JEW-12052 Aug. 9 2010~Oct. 25 2010	7
		FC6JEW-12067~FC6JEW-12071 Oct. 26 2010~Nov. 23 2010	5
		FC6JEW-12082~FC6JEW-12089 Dec. 23 2010~Mar. 25 2011	8
		FC6JEW-12091~FC6JEW-12092 Jun. 24 2011~Jul. 4 2011	2
		FC6JEW-12112~FC6JEW-12113 Apr. 20 2011~Apr. 26 2011	2
		FC6JEW-12116 May. 27 2011	1
		FC6JEW-12119~FC6JEW-12125 May. 18 2011~Jul. 13 2011	7
		FC6JEW-12135~FC6JEW-12136 Jul. 6 2011~Jul. 25 2011	2
		FC6JEW-12138~FC6JEW-12140 Jul. 12 2011~Jul. 26 2011	3
		FC6JEW-12143 Jul. 26 2011	1
		FC6JEW-12145~FC6JEW-12159 Aug. 6 2011~Sep. 20 2011	15
		BDG-FC7JEWA	
SKG-FC9JEAP		FC9JEA-10034 Oct. 7 2011	1
BDG-GX7JKWA		GX7JKW-10058 Sep. 18 2008	1
		GX7JKW-12028 Oct. 19 2010	1
BDG-GC7JEWA		GC7JEW-10100 Jul. 6 2009	1
BKG-GC7JEYA		GC7JEY-10024~GC7JEY-10033 May. 10 2008~Nov. 19 2008	10
		GC7JEY-10038~GC7JEY-10039 Dec. 2 2008~Dec. 8 2008	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
BKG-GC7JEYA	R A N G E R	GC7JEY-12002 Sep. 24 2009	1
		GC7JEY-12032~GC7JEY-12033 Dec. 3 2010~Jan. 13 2011	2
		GC7JEY-12036 Jun. 12 2011	1
		GC7JEY-12040~GC7JEY-12041 Aug. 17 2011~Aug. 19 2011	2
		GC7JEY-12044 Sep. 7 2011	1
BKG-GD7JKYA	R A N G E R	GD7JKY-12038 Sep. 20 2010	1
SKG-GD7JAAA		GD7JKA-10015 Oct. 13 2011	1
		GD7JKA-10017 Oct. 19 2011	1
BDG-MK35C	C O N D O R	MK35C-05275 May. 25 2008	1
		MK35C-15021 Aug. 29 2008	1
		MK35C-15248 Jun. 1 2010	1
		MK35C-15296 Nov. 3 2011	1
PDG-FK71D	F I G H T E R	FK71D-720639 Sep. 9 2008	1
PDG-FK71R		FK71R-540613 Sep. 24 2010	1
		FK71R-541424 Aug. 26 2011	1
PDG-FK62FY		FK62FY-720334 Jul. 14 2009	1
		FK62FY-540029 Sep. 2 2010	1
LKG-FK62FZ		FK62FZ-550189 Apr. 28 2011	1
PKG-FRR90S1		F O R W A R D	FRR90-7006464 Jul. 24 2008
	FRR90-7010304 Sep. 25 2008		1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
PKG-FRR90S1	F O R W A R D	FRR90-7020124 Aug. 27 2010	1
		FRR90-7020398 Sep. 24 2010	1
		FRR90-7026300 Aug. 2 2011	1
PKG-FSR90S2		FSR90-7000324 Sep. 8 2008	1
TOTAL			184