## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2868	DATE	December 13 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In some of the CNG engine-powered garbage trucks, it has been found that one of the rivets to fix reinforcement to the frame was missed. Therefore, high stress will be produced around a hole for the missing rivet in the wake of bending, torsional input, etc., during running. If the affected vehicles are used as they are, there is a possibility that, in the worst case, the frame is cracked.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SFG-NKR82ZAN	ELF	2011	1
SFG-NMR82ZAN		2011	7
		TOTAL	8