

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2875	DATE	December 26,2011
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa city, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	<p>Because the management of the caulking tool for the drain cook pin of the air brake tank was inappropriate, the fixation of O ring of that pin became insufficient. On that account, at the operation of drainage, some O rings come off and air leaks from that pin and then parking brake works.</p> <p>In this condition, as the result, the brake equipments will be overheated and lead to a fire in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
AR139B	—	2010～2011	45
CTB123AJ	—	2010	1
CTB217AA	—	2010	1
CTB22002	—	2010～2011	22
CTB220CJ	—	2010	1
CTB220CM	—	2011	1
CTB220CP	—	2011	4
CTB220CT	—	2010～2011	12
CTB220CU	—	2010	1
CTB220CV	—	2010	2
CTB220CW	—	2010～2011	2
CTB220CZ	—	2010	1
CTB220DC	—	2011	1
CTB220DG	—	2011	1
CTB220DK	—	2011	1
CTB220DM	—	2011	1
CTB229AD	—	2010	5
CTB229AE	—	2010	1
CTB229AF	—	2010～2011	33
CTB24001	—	2010～2011	34
CTB24002	—	2010～2011	10
CTB240BT	—	2010	1
CTB32002	—	2010～2011	143
CTB32003	—	2010～2011	27
CTB32004	—	2010～2011	46
CTB320DM	—	2011	1
CTB320DU	—	2010	2
CTB320DV	—	2010	14
CTB320EE	—	2010～2011	2
CTB320EH	—	2010	1

CTB320EJ	—	2010	1
CTB320ER	—	2011	2
CTB320ES	—	2011	2
CTB320EU	—	2011	3
CTB320EY	—	2011	1
CTB330AA	—	2010	1
CTB335AA	—	2011	1
CTB34003	—	2010~2011	27
CTB34004	—	2010~2011	257
CTB340CA	—	2010	2
CTB340CC	—	2010	1
CTB340CU	—	2011	1
CTS240AP	—	2010	1
CTS240AR	—	2011	1
CTS240BC	—	2010	4
CTS240BE	—	2010	4
CTS240BJ	—	2010	1
CTS240BK	—	2010	26
CTS240BL	—	2010	4
CTS240BM	—	2010	6
CTS240BN	—	2010	10
CTS240BP	—	2010	3
CTS243AD	—	2011	2
CTS245AK	—	2010	6
CTS245AL	—	2010	3
CTS245AM	—	2011	8
CTS34001	—	2011	5
CTS34002	—	2010~2011	92
CTS34003	—	2010~2011	8
CTS34004	—	2010~2011	59
CTS340AU	—	2010	1
CTS340AY	—	2010~2011	18
CTS345AA	—	2011	6
NCCTB32082	—	2010~2011	18
NCCTB34081	—	2010	23
FFB12402	—	2010~2011	63
FFB223AB	—	2011	1
FFB224AA	—	2011	1
FFB224AB	—	2011	1
FFC115BJ	—	2010	1
FFC115BN	—	2010	1
FFG121AJ	—	2011	1
FFS121AE	—	2010	1
FFS122AF	—	2010	1
FFT118AW	—	2010	1

FFT118BC	—	2010	1
FFT118BE	—	2010	1
FFT118BF	—	2011	1
PFB23601	—	2010	3
PFB23904	—	2010~2011	3
PFB23905	—	2010~2011	10
PFB24101	—	2010~2011	18
PFB24102	—	2010~2011	75
PFB24103	—	2010~2011	48
PFB24104	—	2010~2011	18
PFB24111	—	2010~2011	3
PFB325AF	—	2010	1
PFB330BJ	—	2011	1
PFB331BD	—	2011	1
PFB336CS	—	2011	2
PFB339NR	—	2010	1
PFB339PF	—	2011	1
PFB339PG	—	2011	1
PFB339PJ	—	2011	1
PFB34111	—	2010~2011	8
PFB34112	—	2010~2011	125
PFB34113	—	2010~2011	3
PFB34114	—	2010~2011	45
PFB34115	—	2010~2011	4
PFB34116	—	2010~2011	85
PFB34117	—	2010~2011	112
PFB34118	—	2010~2011	20
PFB34119	—	2010~2011	5
PFB34120	—	2010~2011	16
PFC125AM	—	2011	1
PFC239AV	—	2010	1
PFD222BF	—	2011	1
PFD231DS	—	2011	1
PFG236AZ	—	2010	1
PFG238AC	—	2010	1
PFG24111	—	2010~2011	69
PFG241AHD	—	2010	2
PFG242DL	—	2010	2
PFG331AS	—	2010	1
PFG335AP	—	2011	2
PFG339EB	—	2010	1
PFN24101	—	2010~2011	25
PFN24102	—	2010~2011	4
PFN24103	—	2010~2011	168
PFN24104	—	2011	2

PFS230AF	—	2010	1
PFS241BB	—	2010	1
PFS241BF	—	2011	2
PFS241BH	—	2011	1
PFS334AL	—	2011	1
PFS339AR	—	2011	1
PFS342AB	—	2010	2
PFS342AC	—	2011	2
PFU330AB	—	2010	1
PFU331AC	—	2010	1
PFU331AD	—	2011	2
PFU336AK	—	2010	1
PFU339AS	—	2011	1
PFV331AE	—	2010	2
PFV333AM	—	2010	1
PFV336AU	—	2010	1
PFV338AK	—	2010	1
PFV338AL	—	2011	1
PFV339BZ	—	2010	1
PFV339CH	—	2010	3
PFV339CJ	—	2010	3
PFV339CK	—	2010	1
PFV339CM	—	2011	1
PFV339CN	—	2011	2
PFV339CP	—	2011	1
PFW24101	—	2010～2011	87
PFW24102	—	2010～2011	78
PFW24112	—	2010	2
PFW342GM	—	2011	1
PFW342GY	—	2011	1
PFW342GZ	—	2011	2
PLB23901	—	2010	2
PLB24101	—	2010～2011	6
PLB24102	—	2010～2011	7
PLB24103	—	2010～2011	19
PLB24104	—	2010～2011	12
PLB339BD	—	2010	2
PLB34111	—	2010～2011	2
PLB34112	—	2010～2011	38
PLB34113	—	2011	1
PLB341AY	—	2010	2
PLB341BE	—	2011	1
PLB341BF	—	2011	2
PLB341BH	—	2011	5
PLB34201	—	2010	2

PLC241AW	—	2010	1
PLC341AE	—	2010	10
PLF342AC	—	2010	3
PLG341AM	—	2011	1
PLG341AN	—	2010	1
PLG341AP	—	2010	14
PLG341AR	—	2010	2
PLG341AT	—	2011	2
PLR226AD	—	2011	1
PLR339AG	—	2011	1
PLU339AB	—	2010	1
PLW242EG	—	2011	1
PLW342CA	—	2010	4
PLW342CU	—	2011	1
PLW342DB	—	2010	3
PLW344AC	—	2010	1
PLY650AA	—	2011	1
PMB238AB	—	2010	1
PMR237AT	—	2011	1
TBS228AB	—	2010	2
TNF22401	—	2010	2
TNF224AS	—	2010	1
TNF225AM	—	2011	1
TNF228AJ	—	2011	1
TNF234AA	—	2010	1
TNF325AA	—	2011	1
TNF325AB	—	2011	1
TNF325AC	—	2011	2
TNF325AD	—	2011	1
TNF326AA	—	2011	2
TNF326AB	—	2011	2
TNF328AA	—	2010	3
TNF328AB	—	2010	2
TPB314AA	—	2010～2011	4
TPS212AB	—	2010	1
VFB24101	—	2010～2011	83
VFB24102	—	2010～2011	13
VFR341AF	—	2010～2011	4
VFR341AG	—	2010	6
VFR341AH	—	2010	6
VFR342AD	—	2010	2
VFR342AE	—	2011	1
VFR342AF	—	2011	1
VFR345AG	—	2010	4
VFR345AH	—	2010～2011	12

VPB24101	—	2010	3
NT23C013	—	2010	1
NTF8C008	—	2010	1
NTF8C009	—	2010	1
NTF14C004	—	2010	1
NT23C014	—	2010	1
NT25C003	—	2011	1
NT26H011	—	2011	1
NTF8C002	—	2010	2
NT21C035	—	2010	2
NTF8C010	—	2011	1
NTCTB22002	—	2011	2
NTCTB24001	—	2010～2011	11
NTCTB32002	—	2010	3
NTCTB32004	—	2010	2
NTCTB32082	—	2010～2011	17
NTCTB34004	—	2010	4
NTCTB34081	—	2010～2011	10
NTPFB24102	—	2010～2011	4
NTPFN24101	—	2010～2011	22
NTPFW24102	—	2011	10
NTVFB24101	—	2010	1
TOTAL			2609