

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2878	DATE	Jan. 13. 2012
MANUFACTURER	SUMITOMO(S. H. I. ) CONSTRUCTION MACHINERY CO. LTD.		
DESCRIPTION OF DEFECT	IT IS IMPOSSIBLE TO STEER VEHICLE, DUE TO WEAKNESS OF STEERING ROD		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SUMITOMO T60A2 T60WB	SUMITOMO T60A2 T60WB	2005~ 2011	8
TOTAL			8