

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-1818	DATE	February 27, 2012
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	Loss of functionality of the entire rear tail light due to internal Printed Circuit Board (PCB) welded bridge failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MGT	GranTurismo	2008 - 2010	112
ABA-MGTS	GranTurismo S	2008 - 2010	122
ABA-MGTA	GranTurismo S Automatic	2009 - 2010	44
ABA-MGC	GranCabrio	2010	10
		TOTAL	288