VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1821	DATE	2012/03/06	
MANUFACTURE	Daimler AG			
	(Japanese Importer : Mercedes-Benz Japan Co,, Ltd.)			
DESCRIPTION OF DEFECT	Due to improper circuit design at the intake air heating system, circuit of the electric power supply may be damaged and the electric current may keep flowing in case that outside temperature is low. Therefore, if the vehicle is used under this condition continuously, the system may be heated, melted and may not work correctly. As a worst case, it might cause the fire.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
Not applicable	Zetros 1833A	2009 ~ 2009	3
		TOTAL	3
		ICIAL	5