

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	2904	DATE	March 8,2012
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.		
DESCRIPTION OF DEFECT	<p>On some vehicles, the termination did not pass through the fuse, because assembly workers processed them improperly at the time of wiring "Heater relay cable".</p> <p>If the vehicle continues to be used in this condition, the current will become excessive by the cable short-circuit and in the worst case, the cable may burn out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-2GC	MITSUBISHI MOTOR GRADER	2011	28
		TOTAL	28