

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-1830	DATE	Apr 12, 2012
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japoa Ltd. )		
DESCRIPTION OF DEFECT	General Motors has decided to conduct a VOLUNTARY EMISSION RECALL involving certain 2007 model year HUMMER H2 vehicles equipped with a 6.0L V8 engine (LQ4). In these vehicles, the mat support material within the catalytic converter assembly may erode and cause the illumination of the Malfunction Indicator Light and, in some cases, a rattle noise, and/or reduced engine performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	H2	2007	51
		TOTAL	51