VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	Gai-1840	DATE	April 27, 2012		
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)				
DESCRIPTION OF DEFECT	Some vehicles may experience inadvertent ignition key (WIN/FOBIK) displacement from the on to accessory position while driving causing the engine to shut off.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLES
ABA-RT38	Chrysler Grand Voyager	2010		26
			Total	26