

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1855	DATE	July 19, 2012
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the tightening torque of the connection nut between the tie rod end and the pivot on the steering device, the loose of the nut may occur the risk of steering does not operate that come off the tie rod end and the pivot.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A75F01	PEUGEOT 207	2012	3
		TOTAL	3