$\ VEHICLE\ SAFETY\ /\ POLLUTION\ RECALL\ CAMPAIGN\ IN\ JAPAN$

Import Vehicles

CAMPAIN No.	Gai 1862	DATE	July 25, 2012	
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG			
	(Japanese Importer: Porsche Japan KK)			
DESCRIPTION OF DEFECT	Turbochargers, which do not conform to the high Porsche quality			
	standards, were installed in the affected vehicles.			
	As a result, it is possible that the durability of the turbochargers cannot			
	be guaranteed.			
	This can result in engine problems and lack of power. In the worst case scenario, any possible danger due to leaking and igniting engine oil cannot be ruled out.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-970M48A	Panamera Turbo	2011	1
ABA-970M48TA	Panamera Turbo S	2012	18
		TOTAL	19