

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	2996	DATE	27th-Jul-2012
MANUFACTURER	Yano Special Vehicle Manufacturing Co, Ltd		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartmentdoor locks on van-type freight trucks are locked, such red lamps, which canremain lit during travel when a lock is unlocked by a remote key, infringeremain lit during travel when a lock is unlocked by a remote key, infringeon restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-NKR81AN	ELF	2005	1
BDG-NMR85AN		2008	1
PDG-CYJ77W8	GIGA	2008~2009	2
PK-FR1EZWJ	HINO PROFIA	2005	1
KS-FW1EXWG		2006	2
ADG-FR1EZYJ		2006~2007	2
BDG-XZU414M	HINO DUTRO	2008	1
PJ-FU54JUZ	FUSO	2006~2007	2
BJG-FE74B	FUSO CANTER	2007	1
BJG-FE74BV		2008	1
			TOTAL 14