

VEHICLE SAFETY/POLLUTION REGALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2983	DATE	July, 31, 2012
MANUFACTURER	Sapporo Body Industry Corporation		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-FG84D	FUSO CANTER	2011	1
SKG-FEB50		2012	2
BDG-NPS85AN	ELF	2010	1
BKG-NHS85AN		2011	15
		TOTAL	19