

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-1867	DATE	Sep 21th , 2012
MANUFACTURE	CVS : Costruzione Veicoli Speciali (Japanese importer : Hitachi Sumitomo Heavy Industries Construction Crane Co.,Ltd.)		
DESCRIPTION OF DEFECT	As the pressure gauge of the axles which indicates the internal pressure of the container for the breaking device in the vehicle driver's cabin does not have the mark of minimum effective operation pressure level, these vehicles are in non-conformant with road transport vehicle safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	FM4390	1993-1998	11
	FM4410	1990-1998	22
	FM4310	1999-2000	4
	FM5318	1992-2002	19
	FM64300	1998-2001	5
		TOTAL	61