## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic/Import Vehicles

CAMPAIGN No.	3075	DATE	Dec.18.2012	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	On certain heavy city buses , due to an inadequate program in the ECU that controls opening and closing of the rear (slide) door , the door warning lamp (orange) is turned on only when the driver performs the operation to close the door and then tries to open the door just before the door is completely closed; ① In the vehicle equipped with the double solenoid valve, the door stays open. After that, the driver cannot open and close the door from the driver's seat and also the neutral shift lock function that prevents the vehicle from starting with the door opened is disabled. In addition, if the vehicle starts under this condition, the warning buzzer sounds and door warning lamp (red) is turned on. ② In the vehicle equipped with the single solenoid valve, the door stays closed. After that, the driver cannot open and close the door from the driver's seat.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
IIIE	NAME	RECALLED	VEHICLE
LNG-HU8JLGP	HINO Blue Ribbon City	2012	7
LNG-HU8JMGP		2012	1
		TOTAL	8