## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1900	DATE	Jan.30.2013	
MANUFACTURER	NUMMI (TOYOTA)			
DESCRIPTION OF DEFECT	The airbag control module for the supplemental restraint system (SRS) in the subject vehicles could have been manufactured with application-specific integrated circuits (ASICs) that are susceptible to internal shorting. When exposed to high inductive electrical noise from various vehicle electrical components, there is a possibility that the ASIC could become damaged. In the worst case, the front airbag(s) could inadvertently deploy.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF VEHICLE
	NAME	RECALLED	
UA-ZZE136	VOLTZ	2002-2004	3,303
TA-ZZE137		2002-2004	1,125
UA-ZZE138		2002-2004	1,673
		TOTAL	6,101