

VEHICLE SAFETY/POLLUTION REGALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3069	DATE	Feb. 4, 2013
MANUFACTURER	KOSHIDA CORPORATION		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FD1JLEG	HINO PROFIA	2001~2004	6
BKG-XZU344M	HINO DUTRO	2010~2012	6
BDG-FD8JLWG	HINO RANGER	2011~2011	5
BDG-XZU424M	HINO DUTRO	2010~2011	5
SKG-XZU720M	HINO DUTRO	2011	3
TKG-XZU720M	HINO DUTRO	2012	3
BDG-MK37D	CONDOR	2007~2008	3
PB-MK37B	CONDOR	2006~2009	3
EBD-S201C	HIJET	2012	2
KL-CG48ZWV	BIGTHUMB	2010~2012	2
PJ-FS54JZ	FUSO FIGHTER	2006~2007	2
BDG-XZU338M	HINO DUTRO	2009	2
BDG-XZU344M	HINO DUTRO	40196	2
BKG-FW1EXYJ	HINO PROFIA	2009~2010	2
KK-XZU421M	HINO DUTRO	2003	2
LKG-FW1EXBJ	HINO PROFIA	2011~2012	2
LKG-FW1EZBJ	HINO PROFIA	2010~2012	2
PB-XZU344M	HINO DUTRO	2005	2
PK-FW1EZWG	HINO PROFIA	2004~2005	2
PA-FRD34L4	FORWARD	2007	1
SKG-FSR90S2	FORWARD	2012	1
S-NHR55EVN	ELF	1997	1
EBD-S211C	HIJET	2012	1
KC-MK251KH	CONDOR	2011	1
KK-FE63EEV	FUSO CANTER	2008	1
PA-FE70BB	FUSO CANTER	2006	1
PA-FE83DGY	FUSO CANTER	2006	1
PA-FF83DHY	FUSO CANTER	2006	1
PDG-FE83DY	FUSO CANTER	2007	1
PJ-FK65FZ	FUSO CANTER	2006	1
ADG-FD8JLWG	HINO RANGER	2006	1

ADG-FE8JMWG	HINO RANGER	2006	1
BDG-FW1EXYG	HINO PROFIA	2010	1
KK-FD1JLDG	HINO PROFIA	2001	1
KK-XZU411M	HINO DUTRO	2001	1
PB-XZU424M	HINO DUTRO	2006	1
		TOTAL	73