

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1912	DATE	March 12 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The battery-positive cable links the battery with the power distribution box supplying electric power to the vehicle. Due to the inappropriate material for metal coating and configuration of the connector of the battery-positive cable, corrosion may occur because of vehicle vibration and contact resistance may increase. This results in insufficient electric power supply from the power distribution box to the vehicle electrical components, which leads to defect on the electrical components. In worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-UE16	BMW 116i	2007 – 2010	11,659
LBA-UE16		2010 – 2011	4,359
ABA-UD20	BMW 120i	2007 – 2011	5,341
LBA-UD20		2010 – 2011	767
ABA-UD30	BMW 130i	2007 – 2011	1,065
LBA-UC20	BMW 120i Coupe	2010 – 2011	690
ABA-UC30	BMW 135i Coupe	2007 – 2010	394
ABA-UC35		2010 – 2011	1,549
ABA-UL20	BMW 120i Cabriolet	2007 – 2010	1,141
LBA-UM20		2010 – 2011	150
ABA-VA20	BMW 320i	2007 – 2010	16,399
LBA-PG20		2010 – 2011	7,612
LBA-PG20G		2010 – 2011	256
ABA-VB23	BMW 323i	2007	4,296
ABA-VB25	BMW 325i	2007 – 2010	4,188
LBA-PH25		2010 – 2011	639
ABA-VF25	BMW 325Xi	2007 – 2010	111
ABA-PM35	BMW 335i	2010 – 2011	321
ABA-VB35		2007 – 2010	1,436
ABA-VR20	BMW 320i Touring	2007 – 2010	8,330
LBA-US20		2010 – 2011	3,457
ABA-VS25	BMW 325i Touring	2007 – 2010	2,081
LBA-UT25		2010 – 2011	242

ABA-UV35	BMW 335i Touring	2010 – 2011	132
ABA-VS35		2007 – 2010	791
ABA-WA20	BMW 320i Coupe	2007 – 2010	3,688
LBA-KD20		2010 – 2011	606
LBA-KD20G		2010 – 1011	82
LBA-KE25	BMW 325i Coupe	2010 – 2011	293
ABA-KG35	BMW 335i Coupe	2010 – 2011	257
ABA-WB35		2007 – 2010	1,807
ABA-DX35	BMW 335i Cabriolet	2010 – 2011	196
ABA-WL35		2007 – 2010	1,720
ABA-VL18	BMW X1 sDrive 18i	2010 – 2011	6,134
ABA-VL25	BMW X1 xDrive 25i	2010 – 2011	1,370
ABA-LM25	BMW Z4 sDrive 23i	2009 – 2011	2,957
ABA-LM30	BMW Z4 sDrive 35i	2009 – 2011	837
ABA-LM35	BMW Z4 sDrive 35iS	2010 - 2011	104
		TOTAL	97,457