

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1894	DATE	March 22, 2013
MANUFACTURE	Automobiles PEUGEOT, Automobiles CITROEN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	Due to manufacturing error, BSI or built-in system interface with noncompliant specification may have been fitted on the cars. For this reason, the BSI may be unable to control the engine immobilizer and cause engine starting failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-W25F02	PEUGEOT 508	2011-2012	6
ABA-W2W5F02	PEUGEOT 508SW	2012	13
ABA-B75F01	CITROEN C4	2012	1
ABA-B7C5F02S	CITROEN DS4	2011-2012	4
		TOTAL	24