

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1916	DATE	March 22 nd 2013
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH+Co.KG (Japanese Importer: Nicole Racing Japan Co.,Ltd)		
DESCRIPTION OF DEFECT	The battery-positive cable links the battery with the power distribution box supplying electric power to the vehicle. Due to the inappropriate material for metal coating and configuration of the connector of the battery-positive cable, corrosion may occur because of vehicle vibration and contact resistance may increase. This results in insufficient electric power supply from the power distribution box to the vehicle electrical components, which leads to defect on the electrical components. In worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3K20	「B3 Biturbo」	2007 – 2010	143
	「B3 Biturbo Coupe」	2007 – 2009	53
ABA-3K2H	「B3 Biturbo Touring」	2008 – 2009	13
	「B3 Biturbo Cabrio」	2008 – 2009	29
ABA-3K30	「B3S Biturbo」	2010 – 2011	69
	「B3S Biturbo Coupe」	2010 – 2011	17
	「B3S Biturbo Touring」	2010 – 2011	18
	「B3S Biturbo Cabrio」	2010 – 2011	13
		TOTAL	355