VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1928	DATE	May 10 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the missing stamp (of vehicle manufacturer or brand) on the alloy wheels, their compliance with the safety regulation cannot be confirmed. The stamp shall be displayed on the product, of which the conformation to the technical standards defined in the "Technical standards of light alloy disc wheel" is assured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1A16	BMW 116i	2012	118
	BMW 120i	2012	45
LDA-3D20	BMW 320d	2012	126
	BMW 320d Touring	2012	122
LBA-KD20G	BMW 320i Coupe	2010 – 2012	128
LBA-KE25	BMW 325i Coupe	2010 – 2012	63
DBA-3B20	BMW 320i	2012	352
	BMW 320i Touring	2012	13
DBA-3A20	BMW 328i	2011 - 2012	392
	BMW 328i Touring	2012	41
DAA-3F30	BMW ActiveHybrid 3	2012	79
	-1	TOTAL	1,479