

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-1945	DATE	Jun 27, 2013
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect exist in certain 2009-2013 model year Chevrolet Corvette export vehicles that are equipped with an electronic column lock (ECL) may have a condition where the column lock may not unlock when starting the vehicle. This condition could prevent the customer from driving the vehicle because vehicle power would be inhibited by the Powertrain Control Module (PCM). The first time the failure is detected, a "Service Column Lock" DIC message will be displayed with subsequent key cycles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-X245S	「CORVETTE」	2009 – 2011	75
	「CORVETTE Z16」	2012	46
-X245S-		2013	17
ABA-X245A	「CORVETTE ZO6」	2010 – 2012	17
-X245A-	「CORVETTE ZR1」	2010 – 2012	31
		TOTAL	186