VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

			•
CAMPAIGN No.	GAI—1943	DATE	June 27 th , 2013
MANUFACTURE	aprilia		
	(Japanese Importer : Piaggio Group Japan Corp.)		
DESCRIPTION OF DEFECT	Valve Spring Retainer at both intake and exhaust side may possibly have an unexpected wear at continuous high rotational speed due to not enough durability, which may result the breakage of Retainer. By that, Valve may fall into the cylinder inside and engine may be locked, and Bike may be fallen down in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZD4RK	「RSV4 Factory aPRC」 「RSV4 R aPRC」	2012	20 units
		TOTAL	20 units