VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3176	DATE	Jun 24, 2013
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	As 4WD (four-wheel drive) vehicles with Electronic Stability Control faultily got a control program of that for 2WD vehicles, no functioning of the ABS (Antilock Brake System) can have the vehicle resulting in locked tires and losing stability when braking by the driver is slow on such road surfaces as an icy road.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MH34S	WAGON R	2012	1,246
		TOTAL	1,246