

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1939	DATE	June 19, 2013
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Atlantic Cars Limited, Shintoyo Enterprises Ltd, Hakko LR Co., Ltd.)		
DESCRIPTION OF DEFECT	Because the material on the throttle lever did not meet the required standard, the throttle lever could be broken and come off on the continued use. If the throttle lever is come off, the throttle pedal cannot be pushed on and the car cannot be accelerated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	DB9 Coupe, DB9 Volante	2012	9
	V8 Vantage Coupe, V8 Vantage Roadster, V8 Vantage S Coupe, V8 Vantage S Roadster	2012-2013	21

	Virage Coupe, Virage Volante	2012	11
	DBS Coupe, DBS Volante	2012	6
	V12 Vantage Coupe, V12 Vantage Roadster, V12 Zagato	2012	4
	Rapide, Rapide S	2012-2013	23
		TOTAL	74