

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3166	DATE	Jun. 11 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some medium-duty trucks and heavy- and medium-duty buses, the tightening torque for the center head bolts of the air compressor is insufficient, and the pressure change due to the reciprocation of the piston may cause cracks to the seat gasket sealing between the coolant passage and the air passage in the air compressor. Because of this, the coolant may into the air passage, and:</p> <p>(1) The coolant will be sent through the air piping to the air dryer (which is to remove the water and oil from the compressed air) together with the compressed air and discharged outside. As the coolant level will lower, the coolant level warning lamp will illuminate. If the vehicle continues to be used in this condition, the engine power limitation will be applied.</p> <p>(2) The coolant will be dried and crystallized by the heat of the compressed air and the deposit will be stuck on the suction and discharge valves, which will reduce the air volume passing through them. This will result in low air pressure to activate the warning buzzer and the warning lamp. If the vehicle continues to be used in this condition, the vehicle may stop on the road because of insufficient air pressure for the brake system.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FQ62F	「FUSO FIGHTER」	2010 ~ 2012	188
LKG-FK62FZ		2010 ~ 2012	633
LKG-FK65FZ		2010 ~ 2012	447
LKG-FK72FZ		2010 ~ 2012	322
QDG-FQ62F		2011 ~ 2012	143
QKG-FK62FZ		2011 ~ 2012	423
QKG-FK65FZ		2011 ~ 2012	217
QKG-FK72FZ		2010 ~ 2012	171
SKG-FK61F		2010 ~ 2012	928
SKG-FK62FY		2010 ~ 2012	156
SKG-FK64F		2010 ~ 2012	513
SKG-FK65FY		2010 ~ 2012	70
SKG-FK66F		2011 ~ 2012	5
SKG-FK71F		2010 ~ 2013	833
SKG-FK72FY		2010 ~ 2012	170
SKG-FK74F		2011 ~ 2012	74
TKG-FK61F		2011 ~ 2012	976
TKG-FK62FY		2011 ~ 2012	103
TKG-FK64F		2011 ~ 2012	530
TKG-FK65FY		2011 ~ 2012	50
TKG-FK66F	2012 ~ 2012	8	
TKG-FK71F	2011 ~ 2012	932	
TKG-FK72FY	2012 ~ 2012	121	
TKG-FK74F	2012 ~ 2012	72	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-MM96FH	「FUSO AERO ACE」	2011 ~ 2012	6
LKG-MP35FK	「FUSO AERO STAR」	2010 ~ 2012	31
LKG-MP35FM		2010 ~ 2012	245
LKG-MP35FP		2010 ~ 2012	81
LKG-MP37FK		2010 ~ 2012	431
LKG-MP37FM		2010 ~ 2012	93
QDG-MM96FH		「FUSO AERO ACE」	2012 ~ 2012
QDG-MP35FM	「FUSO AERO STAR」	2012 ~ 2012	5
QDG-MP35FP		2012 ~ 2012	8
QKG-MP35FK		2012 ~ 2012	10
QKG-MP35FM		2012 ~ 2012	82
QKG-MP35FP		2012 ~ 2012	57
QKG-MP37FK		2012 ~ 2012	94
QKG-MP37FM		2012 ~ 2012	38
SDG-MM96FH		「FUSO AERO ACE」	2011 ~ 2012
SKG-MK27FH	「FUSO AERO MIDI」	2011 ~ 2012	16
TDG-MM96FH	「FUSO AERO ACE」	2012 ~ 2012	45
TKG-MK27FH	「FUSO AERO MIDI」	2012 ~ 2012	23
LKG-AP35FK	「SPACERUNNER A」	2011 ~ 2011	2
LKG-AP35FM		2010 ~ 2011	20
LKG-AP35FP		2010 ~ 2011	3
LKG-AP37FK		2010 ~ 2011	24
LKG-AP37FM		2010 ~ 2010	5
		TOTAL	9,438