

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1938	DATE	June 06, 2013
MANUFACTURER	S&T Motors Co., Ltd. (Japanese Importer: Japan Auto Press Co., Ltd.)		
DESCRIPTION OF DEFECT	Some brake pads have defect that contact of lining and back-plate is unsuitable by reason of pad material. When the pad has been used for long, the lining is separated from the back-plate and the braking force is deteriorated. In worst case, the lining fall off and the brakes don' t work. (Because one production lot in the brake pads used for the last recall (Campaign No. Gai-1790 issued on Oct. 25, 2011) was unimproved, all vehicles already made replacement by the last recall are recalled again in order to find and replace the unimproved brake pads.)		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GT250R	「GT250R」	2007 - 2010	804
GT250	「GT250」	2007 - 2010	315
GT125R	「GT125R」	2008	1
GT125	「GT125」	2008	5
GV250	「GV250」	2009 - 2010	427
GV125C	「GV125C」	2008 - 2010	217
RT125D	「RT125D」	2007 - 2010	173
RX125SM	「RX125SM」	2007 - 2008	207
RX125D	「RX125D」	2007	92
		TOTAL	2241