

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1954	DATE	July 23, 2013
MANUFACTURE	Automobiles CITROEN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	Due to inferior software integrated with BSI, it may fail to transmit engine start power signal which results engine restart failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-B85F02	CITROEN DS5	2012 - 2013	439
		TOTAL	439