

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -1975	DATE	October 24, 2013
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the fuel level senders on the affected vehicles may not have been calibrated correctly during the production process. As a result, the range on remaining fuel displayed in the instrument cluster might be higher than the actual range. To prevent this from happening, the instrument cluster will be re-coded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-92AM5502	「Cayenne」	2014	3
ABA-92ACGE	「Cayenne S Hybrid」	2014	1
		TOTAL	4