

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3240	DATE	October 18,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>In the rectification work of the brake fluid filling, since the air venting procedure in the brake line is inappropriate, the air may remain in the brake hydraulic unit. As a result, the brake pedal stroke would increase and in the worst case scenario, the braking effect could be deteriorated. In the vehicles with ASC (Active Stability Control system), the sideslip prevention function could be impaired.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-A05A	「MIRAGE」	2012~2013	103
		TOTAL	103