

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	3238	DATE	OCT.3.2013
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium duty trucks that spread antifreeze agent, since the durability of the nylon air tube for the rear wheel parking brake is insufficient, when driving on snowy roads, snow that adheres to the tube may freeze and form packs that place heavy load on the tube. This can cause cracking in the tube and the wheel parking brake to be functioned by a leakage of the brake air resulting the vehicle unable to move if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-GX1JGEA	「HINO Ranger」	2002~2003	68
PB-GX7JGFA		2004~2005	43
ADG-GX7JGWA		2005~2010	263
BDG-GX7JGWA			
SDG-GX7JGAA		2011~2012	101
		TOTAL	475