

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1983	DATE	November 12 th , 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the possibly missing stamp (of vehicle manufacturer or brand) on the alloy wheels, their compliance with the safety regulation may not be confirmed. The stamp shall be displayed on the product, of which the conformation to the technical standards defined in the “Technical standards of light alloy disc wheel” is assured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LL20	BMW Z4 sDrive 20i	2013	47
ABA-LM30	BMW Z4 sDrive 35i	2013	3
		TOTAL	50