

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1979	DATE	Nov.7.2013
MANUFACTURER	TMUK TOYOTA		
DESCRIPTION OF DEFECT	The frontal protection airbag warning label affixed on the passenger side sun visor does not meet the requirement of the warning label prescribed in the Safety Regulation Section 18-22.9.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRT272W	[AVENSIS]	2013	399
		TOTAL	399