VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1984	DATE	Dec. 4, 2013	
MANUFACTURER	Automobili Lamborghini S.p.A. (Japanese Importer : Audi Japan KK)			
DESCRIPTION OF DEFECT	Technical background; On vehicles fitted with carbon ceramic brakes, the stainless steel screws fixing the rotor to the metal bell may fail due to stress corrosion cracking, if the vehicle has been used in extremely salty environments. Remedy; On the affected vehicles the fasteners on the ceramic brakes must be replaced with improved fasteners in accordance with the Repair Instructions.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GH-BC10E	Murcielago	2006	7
ABA-BE537	Murcielago LP640 / Reventon	2007 -2009	82
ABA-BE537A	Murcielago LP640	2010	3
ABA-BE538	Murcielago LP670-4SV	2010	20
GH-JFGE12	Gallardo / Gallardo Spyder	2007	5
ABA-GECEH	Gallardo LP560-4	2009	10
ABA-GE07L2	Gallardo SL	2008	27
ABA-GE07L1	Gallardo Spyder	2008	2
		TOTAL	156