

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	Gai-1989	DATE	Dec. 3. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In rare cases fault entry is written into the fault memory of the Engine control unit. The result is that the motorcycle switches to an emergency operation program. Depending on operating condition, the possibility of the engine shutting down under these circumstances cannot be precluded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-K16AA	K1600GTL	2012-2013	386
		TOTAL	386