VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3324	DATE	March 6 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy duty sightseeing buses,in oil piping of the transmission,due to inadequate tightening of the connector attached to the oil filter, there are some from which oil leaks. If the vehicle is operated under the condition continuously, in the worst case, there is a possibility that the transmission is seizured and driving may become impossible.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
BDG-RU8JHAJ	[ISUZU GALA]	2010	15
LDG-RU8JHBJ SDG-RU8JHBJ		2010-2014	103
		TOTAL	118