

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2031	DATE	May 1st, 2014
MANUFACTURE	Harley Davidson Motor Company (Japanese Importer : Harley Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	Some of these motorcycles may run out of fuel while the fuel range indicator shows miles remaining, in some cases before the low fuel warning lamp illuminates. If this condition remains undetected it could cause the engine to stop running unexpectedly. While in traffic, a stall can possibly lead to a crash. Harley-Davidson has initiated this recall to correct this condition in the affected motorcycles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BF5	BREAKOUT	2013 (MY)	268
BF5	BREAKOUT	2014 (MY)	625
TD9	CVO™ BREAKOUT	2013 (MY)	353
TD9	CVO™ BREAKOUT	2014 (MY)	185
		TOTAL	1431