

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2049	DATE	June 17th, 2014
MANUFACTURE	Harley Davidson Motor Company (Japanese Importer : Harley Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	<p>Harley-Davidson Motor Company, Inc. has decided that a defect related to motor vehicle safety may exist in certain accessory Chrome Hand Control Lever Kits, P/N 36700053, intended for dealer or customer installation on model year 2014 XL Sportster models. The affected kits will have a package date that is earlier than 5/08/2014, although not all of these accessory kits may contain the defect.</p> <p>Some of these accessory kits may contain brake levers with excessive chrome plating. In extreme cases this could prevent complete return of the master cylinder piston. If the piston cannot completely return and uncover the port-timing hole, fluid pressure will not be relieved. If this condition remains undetected, it could cause the fluid pressure to increase, possibly resulting in a front wheel lock-up, which could lead to a crash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-1200CN	SEVENTY-TWO	2014 (MY)	7
EBL-1200CN	1200CA LIMITED	2014 (MY)	1
EBL-883RN	SUPERLOW	2014 (MY)	1
		TOTAL	9