## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-2072	DATE	Jul. 25th, 2014
MANUFACTURER	ALPINA Brukard Bovensiepen Gmbh+Co.KG (Japanese Importer: Nicole Racing Japan Co.,Ltd)		
DESCRIPTION OF DEFECT	The software of engine control unit is not proper. Therefore, when the control unit detects defects relevant to boost control, it doesn't switches to emergency mode, engine may stop and be impossible to start it again.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-5M1C	B5 Biturbo	2012 $\sim$ 2013	66
ABA-5M1A	B5 Biturbo Touring	2012 $\sim$ 2013	9
ABA-6M10	B6 Biturbo Coupe	2012	8
	B6 Biturbo Cabrio	2012	5
		TOTAL	88